






























Revit Keyboard Shortcuts (KS)

Top 10 - User defined

1. Naviate Filter Elements	(FF)		
2. Select All Instances In: In Entire Project	(SA) / (Ctrl+A)		Right-click
3. Default 3D View	(Fn3)		
4. Move (Mirror (MM) (MI))	(MM)		
5. Align (Adjusts the analytical model)	(AA)		
6. Measure Between Two References	(Fn4)		
7. Pick Lines	(PL)		
8. Finish...	(Fn6)		
9. Orient to Other View	(OV)		Right-click 
10. Join	(JJ)		

Top 10 - Most used

1. (Ctrl+...)	Undo	(Ctrl+Z)		
	Save	(Ctrl+S)		
	New Project	(Ctrl+N)		
	Select All Instances In: In Entire Project	(Ctrl+A)		Right-click <i>Custom</i>
	Switch Window	(Ctrl+Tab)		
	Properties	(Ctrl+1)		
2. (Modify)	Modify	(Esc)		
	Move	(MM)		<i>Custom</i>
	Copy	(CC)		
	Align	(AA)		
	Join	(JJ)		<i>Custom</i>
3. Visibility/ Graphics		(VV)		
4. Select Previous		(PP)		Right-click
5. (Temp Hide/Isolate)	Temporary Hide Element	(HH)		
	Temporary Isolate Element	(HI)		
	Temporary Hide Category	(HC)		
	Temporary Isolate Category	(IC)		
	Reset Temporary Hide/Isolate	(HR)		
	Hide in View → Category	(VH)		Right-click
	Hide in View → Elements	(EH)		Right-click
6. Naviate Filter Elements		(FF)		<i>Custom</i>
7. Default 3D View		(Fn3)		<i>Custom</i>
8. Measure Between Two References		(Fn4)		<i>Custom</i>
9. Aligned Dimension		(DI)		
10. Rotate with 'Relocates center of rotation'		(R3)	